
## **Sensor Installation**

- Attach an arm to the rotating sensor bracket (2 x M6 screws)
  Use thin flat bar or lightweight rod



• Attach to the machine linkage with a rod or flat bar assembly

