


SPREADER RATE CONTROLLER HARNESS HK0107

See your Operators Manual for a complete setup guide. Info here covers important hardware settings only.


OUTLINE

- Basic install shown below
- Rate controller mounted on spreader



CONTROLLER SETTINGS

- Select MENU > RATE CONTROLLER > IMPLEMENT SETUP > BIN1 SETUP
- Enter settings shown below for BIN1 SETUP
- Enter settings shown below for PWM SETTINGS
- Select PRODUCT SETUP > PRODUCT BIN SETUP > BIN1 SETUP
- Enter settings shown below for BIN1 PRODUCT SETUP



Conveyor Speed Sensor Calibration

- Is the number of pulses from the sensor, during one revolution of the rear roller (not the whole belt)
- Values between 100 and 1500 perform best

<u>CFR</u>

- Is the cubic cm volume dispensed during one revolution of the rear roller, with the gate at 1cm high
- Values between 1000 and 6000 perform best

HARNESS WIRING

- IMPORTANT: Belt sensor and spinner sensors are wired to 12volt supplies
- Do not connect them to 5volt sensors/encoders
- Pin26 in the rate controller connectors can be swapped to 5volt supplies if requred
- Valve is wired for PWM solenoid valve

1	PIN 1	BLACK	VALVE GROUND]
	PIN 5	RED	POSITIVE PWM	PWM VALVE BELT
			_]
	PIN 28	YELLOW	BELT SPEED SIGNAL]
	PIN 27	PLACK	SENSOR GROUND	BELT SPEED SENSOR
	PIN 26	RED	SENSOR 12V	
I			_]
	PIN 27	BLACK	SENSOR GROUND	
	PIN 26	RED	SENSOR 12V	SPINNER SPEED SENSOR
	PIN 25 -	ORANGE	SPINNER SPEED SIGNAL	SENSOR
			-	Ţ

CORROSION

Regularly apply corrosion protectant to the connector pins (dielectric grease / electrical silicone spray / marine protectant / water dispersant etc). Contact cleaner will clean the pins but it <u>will not prevent corrosion</u>. Filling the rear of the connector with silicone sealant will trap moisture and cause failure.

All brands, product names, company names, trademarks referred to herein, are the property of their respective trademark holders. Use of them does not imply any affiliation with, or endorsement by them.